


Instruction Sheet
SealSmart Coaxial Cable Strippers

SealSmart
IS15021

Cable Stripping & Termination

1. Cable strippers are color coded for cable type (see chart).
2. Open tool and place cable in tool. Close tool.
3. Using forefinger, rotate tool around cable 4-5 times.
4. Grasp jaws of tool with thumb & forefinger, hold closed.
5. Pull stripper straight off end of cable while holding closed.
6. Remove stripped cable & dielectric from jaws of tool.
7. Trim center conductor to proper length.
8. If using SealSmart Compression connector, fold braid back over cable jacket prior to insertion into connector.



No adjustments required!

Cable	Tool Color	P/N
RG6 Quad	Blue	15021
RG6	Black	15022
RG59	Red	15023